

Report of Analysis

Client: VERINA CONSULTING GROUP, LLC
Project: Rotor Clip NJ WTD - 2025
Client Sample ID: WATER-TREATMENT DISCHARGE
Lab Sample ID: Q3785-01

Date Collected: 12/04/25 11:00
Date Received: 12/04/25
SDG No.: Q3785
Matrix: WATER
% Solid: 0

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Cyanide	0.00096	U	1	0.00096	0.0050	mg/L	12/08/25 08:50	12/08/25 12:55	9012B
Oil and Grease	3.30	J	1	0.29	5.00	mg/L		12/08/25 12:37	1664A

Comments: _____

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N = Spiked sample recovery not within control limits