

Report of Analysis

Client: VERINA CONSULTING GROUP, LLC
Project: Rotor Clip NJ WTD - 2025
Client Sample ID: WATER-TREATMENT DISCHARGE
Lab Sample ID: Q3785-04
Level (low/med): low

Date Collected: 12/04/25
Date Received: 12/04/25
SDG No.: Q3785
Matrix: Water
% Solid: 0

Cas	Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.	Prep Met.
7440-43-9	Cadmium	0.25	UN	1	0.25	3.00	ug/L	12/05/25 10:40	12/09/25 19:56	6010D	M3010A
7440-47-3	Chromium	2.68	J	1	1.06	5.00	ug/L	12/05/25 10:40	12/09/25 19:56	6010D	M3010A
7440-50-8	Copper	7.87	J	1	2.30	10.0	ug/L	12/05/25 10:40	12/09/25 19:56	6010D	M3010A
7439-92-1	Lead	1.15	U	1	1.15	6.00	ug/L	12/05/25 10:40	12/09/25 19:56	6010D	M3010A
7440-02-0	Nickel	3.50	J	1	1.53	20.0	ug/L	12/05/25 10:40	12/09/25 19:56	6010D	M3010A
7440-22-4	Silver	0.81	UN	1	0.81	5.00	ug/L	12/05/25 10:40	12/09/25 19:56	6010D	M3010A
7440-66-6	Zinc	163		1	8.33	20.0	ug/L	12/05/25 10:40	12/09/25 19:56	6010D	M3010A

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N = Spiked sample recovery not within control limits