

284 Sheffield Street, Mountainside, New Jersey 07092, Phone : 908 789 8900, Fax : 908 789 8922

## - COVER PAGE -INORGANIC ANALYSIS DATA PACKAGE

Client:	Tully Construction Co., Inc.				
SDG No.:	Q3790				
Contract:	TULL02		Lab Code: ACE		
	Lab Sample ID		Client Sample II	)	QC Description
	Q3790-01		304 FURMAN SOIL		<u> </u>
	Q3795-01DUP		72-11966DUP		Sample Duplicate
	Q3795-01MS		72-11966MS		Matrix Spike
	Q3795-01MSD		72-11966MSD		Matrix Spike Duplicate
	Q3806-04DUP		TR-05-12-5-2025DU	ΙΡ	Sample Duplicate
	Q3806-04MS		TR-05-12-5-2025MS	}	Matrix Spike
	Q3806-04MSD		TR-05-12-5-2025MS	SD	Matrix Spike Duplicate
Were ICP interv	element corrections applied?	Yes/No			
Were ICP background corrections applied?		Yes/No			
If yes - were raw data generated before applications of background corrections?		Yes/No			
Comments:					
contract, both to above. Release	s data package is in compliance echnically and for completeness of the data contained in this ha ne Laboratory Manager or the M	s, for other than the rdcopy data packag	conditions detailed se and in the computer-r		ed on diskette has been
contract, both to above. Release	echnically and for completeness of the data contained in this ha ne Laboratory Manager or the M	s, for other than the rdcopy data packag	conditions detailed se and in the computer-r		ed on diskette has been