



284 Sheffield Street, Mountainside, New Jersey 07092, Phone : 908 789 8900,
Fax : 908 789 8922

Hit Summary Sheet
SW-846

SDG No.: Q3790

Order ID: Q3790

Client: Tully Construction Co., Inc.

Project ID: MTA 26 Stations - Pierrepont

Sample ID	Client ID	Matrix	Parameter	Concentration	C	MDL	RDL	Units
-----------	-----------	--------	-----------	---------------	---	-----	-----	-------

Client ID :

Total Concentration: 0.000

A

B

C

D



SAMPLE DATA

A

B

C

D

Report of Analysis

Client:	Tully Construction Co., Inc.		Date Collected:	12/05/25
Project:	MTA 26 Stations - Pierrepont		Date Received:	12/05/25
Client Sample ID:	304 FURMAN SOIL		SDG No.:	Q3790
Lab Sample ID:	Q3790-01		Matrix:	SOIL
Analytical Method:	8082A		% Solid:	86.3
Sample Wt/Vol:	30.09 g	Final Vol: 10000 uL	Test:	PCB
Prep Method:	SW3541B	Prep Date: 12/08/25		

CAS Number	Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Date Ana.	BatchID
TARGETS									
12674-11-2	Aroclor-1016	0.0046	U	1	0.0046	0.020	mg/Kg	12/08/25 15:09	PB170862
11104-28-2	Aroclor-1221	0.0047	U	1	0.0047	0.020	mg/Kg	12/08/25 15:09	PB170862
11141-16-5	Aroclor-1232	0.0043	U	1	0.0043	0.020	mg/Kg	12/08/25 15:09	PB170862
53469-21-9	Aroclor-1242	0.0046	U	1	0.0046	0.020	mg/Kg	12/08/25 15:09	PB170862
12672-29-6	Aroclor-1248	0.0068	U	1	0.0068	0.020	mg/Kg	12/08/25 15:09	PB170862
11097-69-1	Aroclor-1254	0.0037	U	1	0.0037	0.020	mg/Kg	12/08/25 15:09	PB170862
37324-23-5	Aroclor-1262	0.0058	U	1	0.0058	0.020	mg/Kg	12/08/25 15:09	PB170862
11100-14-4	Aroclor-1268	0.0042	U	1	0.0042	0.020	mg/Kg	12/08/25 15:09	PB170862
11096-82-5	Aroclor-1260	0.0037	U	1	0.0037	0.020	mg/Kg	12/08/25 15:09	PB170862
SURROGATES									
877-09-8	Tetrachloro-m-xylene	21.4			21 - 165	107%	SPK: 20		
2051-24-3	Decachlorobiphenyl	14.1			10 - 170	70%	SPK: 20		

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

E = Value Exceeds Calibration Range

P = Indicates >25% difference for detected concentrations between the two GC columns

Q = indicates LCS control criteria did not meet requirements

M = MS/MSD acceptance criteria did not meet requirements

J = Estimated Value

B = Analyte Found in Associated Method Blank

N = Presumptive Evidence of a Compound

* = Values outside of QC limits

D = Dilution

S = Indicates estimated value where valid five-point calibration was not performed prior to analyte detection in sample.

() = Laboratory InHouse Limit

LAB CHRONICLE

OrderID:	Q3790	OrderDate:	12/5/2025 10:01:00 AM
Client:	Tully Construction Co., Inc.	Project:	MTA 26 Stations - Pierreport
Contact:	Dean Devoe	Location:	D31,VOA Lab

LabID	ClientID	Matrix	Test	Method	Sample Date	Prep Date	Anal Date	Received
Q3790-01	304 FURMAN SOIL	SOIL	PCB	8082A	12/05/25	12/08/25	12/08/25	12/05/25