

Report of Analysis

Client:	Tully Construction Co., Inc.	Date Collected:	12/05/25
Project:	MTA 26 Stations - Pierrepont	Date Received:	12/05/25
Client Sample ID:	304 FURMAN SOIL-TPH-1	SDG No.:	Q3790
Lab Sample ID:	Q3790-04	Matrix:	SOIL
Analytical Method:	8015D TPH	% Solid:	86.9
Sample Wt/Vol:	30.04 g	Final Vol:	1 mL
Prep Method:	SW3541	Test:	TPH GC
	Prep Date:	12/09/25	

CAS Number	Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Date Ana.	BatchID
TARGETS									
PHC	Petroleum Hydrocarbons	19.4		1	0.44	3.26	mg/Kg	12/10/25 11:37	PB170872
SURROGATES									
16416-32-3	TETRACOSANE-d50	15.8			37 - 130	79%	SPK: 20		

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

E = Value Exceeds Calibration Range

P = Indicates >25% difference for detected concentrations between the two GC columns

Q = indicates LCS control criteria did not meet requirements

M = MS/MSD acceptance criteria did not meet requirements

J = Estimated Value

B = Analyte Found in Associated Method Blank

N = Presumptive Evidence of a Compound

* = Values outside of QC limits

D = Dilution

S = Indicates estimated value where valid five-point calibration was not performed prior to analyte detection in sample.

() = Laboratory InHouse Limit