



284 Sheffield Street, Mountainside, New Jersey 07092, Phone : 908 789 8900,
Fax : 908 789 8922

Hit Summary Sheet SW-846

SDG No.: Q3790

Client: Tully Construction Co., Inc.

Sample ID	Client ID	Matrix	Parameter	Concentration	C	MDL	RDL	Units
Client ID : 304 FURMAN SOIL								
Q3790-01	304 FURMAN SOIL	SOIL	Phenanthrene	0.220		0.024	0.20	mg/Kg
Q3790-01	304 FURMAN SOIL	SOIL	Fluoranthene	0.320		0.035	0.20	mg/Kg
Q3790-01	304 FURMAN SOIL	SOIL	Pyrene	0.330		0.042	0.20	mg/Kg
Q3790-01	304 FURMAN SOIL	SOIL	Benzo(a)anthracene	0.170	J	0.027	0.20	mg/Kg
Q3790-01	304 FURMAN SOIL	SOIL	Chrysene	0.160	J	0.023	0.20	mg/Kg
Q3790-01	304 FURMAN SOIL	SOIL	Benzo(b)fluoranthene	0.230		0.022	0.20	mg/Kg
Q3790-01	304 FURMAN SOIL	SOIL	Benzo(a)pyrene	0.160	J	0.034	0.20	mg/Kg
Q3790-01	304 FURMAN SOIL	SOIL	Indeno(1,2,3-cd)pyrene	0.100	J	0.034	0.20	mg/Kg
Q3790-01	304 FURMAN SOIL	SOIL	Benzo(g,h,i)perylene	0.130	J	0.030	0.20	mg/Kg
Total Svoc :				1.82				
Total Concentration:				1.82				