

Surrogate Summary

SW-846

SDG No.: Q3790

Client: Tully Construction Co., Inc.

Analytical Method: 8270E

Lab Sample ID	Client ID	Parameter	Spike (PPM)	Result (PPM)	Recovery (%)	Qual	Limits (%)	
							Low	High
PB170865BL	PB170865BL	Nitrobenzene-d5	100	87.9	88		10	108
		2-Fluorobiphenyl	100	92.4	92		10	108
		Terphenyl-d14	100	97.0	97		10	109
PB170865BS	PB170865BS	Nitrobenzene-d5	100	78.5	79		10	108
		2-Fluorobiphenyl	100	78.9	79		10	108
		Terphenyl-d14	100	82.1	82		10	109
Q3790-01	304 FURMAN SOIL	Nitrobenzene-d5	100	42.9	43		10	108
		2-Fluorobiphenyl	100	47.7	48		10	108
		Terphenyl-d14	100	49.0	49		10	109
Q3795-01MS	72-11966MS	Nitrobenzene-d5	100	62.8	63		10	108
		2-Fluorobiphenyl	100	64.2	64		10	108
		Terphenyl-d14	100	82.6	83		10	109
Q3795-01MSD	72-11966MSD	Nitrobenzene-d5	100	58.4	58		10	108
		2-Fluorobiphenyl	100	58.8	59		10	108
		Terphenyl-d14	100	67.2	67		10	109