

Surrogate Summary

SDG No.: Q3790

Client: Tully Construction Co., Inc.

Analytical Method: SW8260D

Lab Sample ID	Client ID	Parameter	Spike	Result	Recovery (%)	Qual	Limits (%)	
							Low	High
Q3790-03	304 FURMAN SOIL	1,2-Dichloroethane-d4	50	38.5	77		63	155
		Dibromofluoromethane	50	38.6	77		70	134
		Toluene-d8	50	32.4	65	*	74	123
		4-Bromofluorobenzene	50	26.6	53		52	138
VW1208SBL01	VW1208SBL01	1,2-Dichloroethane-d4	50	54.2	108		63	155
		Dibromofluoromethane	50	50.7	101		70	134
		Toluene-d8	50	49.3	99		74	123
		4-Bromofluorobenzene	50	45.1	90		52	138
VW1208SBS01	VW1208SBS01	1,2-Dichloroethane-d4	50	50.1	100		63	155
		Dibromofluoromethane	50	48.5	97		70	134
		Toluene-d8	50	47.7	95		74	123
		4-Bromofluorobenzene	50	47.3	95		52	138
VW1208SBSD0	VW1208SBSD01	1,2-Dichloroethane-d4	50	55.6	111		63	155
		Dibromofluoromethane	50	54.4	109		70	134
		Toluene-d8	50	55.7	111		74	123
		4-Bromofluorobenzene	50	53.4	107		52	138