

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

## **Report of Analysis**

Client: PSEG

Project: PSEG South Clifton Ave Property

Client Sample ID: TP-13 Lab Sample ID: Q3826-02 Date Collected: 12/09/25 11:06

100

Date Received: 12/09/25 SDG No.: Q3826 Matrix: SOIL

% Solid:

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.	
Corrosivity	5.45	Н	1	0	0	рН		12/10/25 10:19	9045D	
Ignitability	NO		1	0	0	oC		12/10/25 08:49	1030	
Reactive Cyanide	0.049	U	1	0.0083	0.049	mg/Kg	12/10/25 12:00	12/10/25 14:32	9012B	
Reactive Sulfide	1.59	J	1	0.20	10.0	mg/Kg	12/11/25 09:30	12/11/25 11:33	9034	

Comments: pH result reported at temperature 20.6 °C

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

\* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits