

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

## **Report of Analysis**

Client: CHA Companies, Inc.

Project: NYSOMH Emergency Service Client Sample ID: B2-W14-RM3075-SINK

Lab Sample ID: Q3841-02

Date Collected: 12/11/25 09:45

Date Received: 12/11/25 SDG No.: Q3841 Matrix: Water

% Solid: 0

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Residual Chlorine	0.20	Н	1	0.023	0.10	mg/L		12/11/25 16:38	SM 4500-C1 G-11
Turbidity	1.00	J	1	0.15	1.00	NTU		12/12/25 10:06	_

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

\* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits