



284 Sheffield Street, Mountainside, New Jersey 07092, Phone : 908 789 8900,
Fax : 908 789 8922

Initial and Continuing Calibration Verification

Client: CHA Companies, Inc.

SDG No.: Q3841

Project: NYSOMH Emergency Service

RunNo.: LB138205

Analyte	Units	Result	True Value	% Recovery	Acceptance Window (%R)	Analysis Date
Sample ID: ICV Residual Chlorine	mg/L	0.409	0.4	102	90-110	12/11/2025
Sample ID: CCV1 Residual Chlorine	mg/L	0.389	0.4	97	90-110	12/11/2025
Sample ID: CCV2 Residual Chlorine	mg/L	0.399	0.4	100	90-110	12/11/2025
Sample ID: CCV3 Residual Chlorine	mg/L	0.399	0.4	100	90-110	12/11/2025

Initial and Continuing Calibration Verification

Client: CHA Companies, Inc.

SDG No.: Q3841

Project: NYSOMH Emergency Service

RunNo.: LB138208

Analyte		Units	Result	True Value	% Recovery	Acceptance Window (%R)	Analysis Date
Sample ID: Turbidity	ICV	NTU	10.235	10	102	90-110	12/12/2025
Sample ID: Turbidity	CCV1	NTU	9.300	10	93	90-110	12/12/2025
Sample ID: Turbidity	CCV2	NTU	9.674	10	97	90-110	12/12/2025