

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

## **Report of Analysis**

Client: **PSEG** Date Collected: 12/11/25 14:00

Project: Burlington Gas and Appliance Service (BU) Date Received: 12/11/25 Client Sample ID: BU-02-12112025 SDG No.: Q3846 Lab Sample ID: Q3846-01 Matrix: SOIL

% Solid: 91.6

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Cyanide	0.26	U	1	0.044	0.26	mg/Kg	12/15/25 08:20	12/15/25 10:38	9012B
pH	7.90	Н	1	0	0	pН		12/12/25 09:30	9045D

Comments: pH result reported at temperature 20.7 °C

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

\* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits