

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

## **Report of Analysis**

Client: PSEG Date Collected: 12/12/25 08:51
Project: Hackensack - Palisades Electric Division Sub HQ Date Received: 12/12/25

Project: Hackensack - Palisades Electric Division Sub HQ Date Received: 12/12/25

Client Sample ID: ETGI-360 SDG No.: Q3854

Lab Sample ID: Q3854-01 Matrix: SOIL

% Solid: 92.1

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Cyanide	0.076	J	1	0.044	0.26	mg/Kg	12/15/25 08:20	12/15/25 10:45	9012B
Hexavalent Chromium	0.074	U	1	0.074	0.42	mg/Kg	12/15/25 08:50	12/15/25 12:17	7196A
Paint Filter	1.00	U	1	1.00	1.00	ml/100gm		12/16/25 09:09	9095B

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

\* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits