

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: PSEG Date Collected: 12/12/25 09:08

Project: Hackensack - Palisades Electric Division Sub HQ Date Received: 12/12/25
Client Sample ID: 326 SDG No.: Q3855
Lab Sample ID: Q3855-02 Matrix: SOIL
% Solid: 100

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Corrosivity	5.84	Н	1	0	0	рН		12/15/25 10:55	9045D
Ignitability	NO		1	0	0	oC		12/16/25 11:25	1030
Reactive Cyanide	0.049	U	1	0.0083	0.049	mg/Kg	12/15/25 10:25	12/15/25 13:18	9012B
Reactive Sulfide	6.36	J	1	0.20	10.0	mg/Kg	12/16/25 09:30	12/16/25 13:24	9034

Comments: pH result reported at temperature 22.6 °C

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits