

LAB CHRONICLE

OrderID: Q3881	OrderDate: 12/15/2025 3:02:08 PM
Client: JPCL Engineering	Project: Sunnyside Yard
Contact: Paul Rotondi	Location: --Select--,D31,VOA Ref. #2 Soil

LabID	ClientID	Matrix	Test	Method	Sample Date	Prep Date	Anal Date	Received
Q3881-03	DM-X-76	SOIL			12/15/25 12:00			12/15/25
			Corrosivity	9045D			12/16/25 09:37	
			Ignitability	1030			12/16/25 14:30	
			Reactive Cyanide	9012B		12/17/25	12/17/25 13:23	
			Reactive Sulfide	9034		12/16/25	12/16/25 13:50	