



Analytical Summary Report

Analysis Method: 9095B

Reviewed By: Vanita

Parameter: Paint Filter

Supervisor Review By: ketankumar

Run Number: LB101904

BalanceID: WC SC-4

Seq	LabID	ClientID	Dilution	Weight(g)	Inst. Conc (ml/100g)	Anal Date	Anal Time
1	K2264-01	OPEN-WALL-EXCAVATIOI	1	100.06	0.00	04/05/2019	09:35
2	K2264-01DUP	OPEN-WALL-EXCAVATIOI	1	100.01	0.00	04/05/2019	09:42
3	K2264-04	293-72-11966-238	1	100.07	0.00	04/05/2019	09:51

WORKLIST(Hardcopy Internal Chain)

LB101904

WorkList Name : PF4519

WorkList ID : 124446

Date : 04-05-2019 09:16:04

Due Date	Matrix	Sample	Test	Preservative	Customer	Storage Location	Customer Sample	Collect Date	Method
04/04/2019	Solid	K2264-01	Paint Filter	Cool 4 deg C	PSEG01	K31	OPEN-WALL-EXCAVATION	04/04/2019	9095B
04/04/2019	Solid	K2264-04	Paint Filter	Cool 4 deg C	PSEG01	K31	293-72-11966-238	04/04/2019	9095B

Date/Time 04/05/19 9:20
 Received by: VR
 Relinquished by: CP

Date/Time 04/05/2019 9:55
 Received by: CP
 Relinquished by: VR