



Analytical Summary Report

Analysis Method: 9095B
Parameter: Paint Filter
Run Number: LB101928

Reviewed By: Vanita
Supervisor Review By: ketankumar
BalanceID: WC SC-4

Seq	LabID	ClientID	Dilution	Weight(g)	Inst. Conc (ml/100g)	Anal Date	Anal Time
1	K2240-13	SB-01-COMP	1	100.07	0.00	04/08/2019	09:40
2	K2240-13DUP	SB-01-COMPDUP	1	100.04	0.00	04/08/2019	09:47
3	K2240-17	SB-02-COMP	1	100.03	0.00	04/08/2019	09:55
4	K2240-19	SB-03-COMP	1	100.08	0.00	04/08/2019	10:03
5	K2294-03	TP-14-S	1	100.02	0.00	04/08/2019	10:11
6	K2294-07	TP-14-D	1	100.05	0.00	04/08/2019	10:18
7	K2309-01	HA-040519	1	100.04	0.00	04/08/2019	10:25

WORKLIST(Hardcopy Internal Chain)

LB101928

WorkList Name : PF4819

WorkList ID : 124509

Date : 04-08-2019 09:20:35

Due Date	Matrix	Sample	Test	Preservative	Customer	Storage Location	Customer Sample	Collect Date	Method
04/02/2019	Solid	K2240-13	Paint Filter	Cool 4 deg C	LIRO01	F51	SB-01-COMP	04/02/2019	9095B
04/02/2019	Solid	K2240-17	Paint Filter	Cool 4 deg C	LIRO01	F51	SB-02-COMP	04/02/2019	9095B
04/02/2019	Solid	K2240-19	Paint Filter	Cool 4 deg C	LIRO01	F51	SB-03-COMP	04/02/2019	9095B
04/05/2019	Solid	K2294-03	Paint Filter	Cool 4 deg C	PSEG01	K31	TP-14-S	04/05/2019	9095B
04/05/2019	Solid	K2294-07	Paint Filter	Cool 4 deg C	PSEG01	K31	TP-14-D	04/05/2019	9095B
04/05/2019	Solid	K2309-01	Paint Filter	Cool 4 deg C	PSEG01	K31	HA-040519	04/05/2019	9095B

Date/Time 04-08/2019 9:25
 Received by: VR
 Relinquished by: 

Date/Time 04-08/2019 10:35
 Received by: 
 Relinquished by: VR