



Analytical Summary Report

Analysis Method: 9095B

Reviewed By: ketankumar

Parameter: Paint Filter

Supervisor Review By: apatel

Run Number: LB102727

BalanceID: WC SC-4

Seq	LabID	ClientID	Dilution	Weight(g)	Inst.Conc (ml/100g)	Anal Date	Anal Time
1	K2808-01	RT-2683-RT-5156	1	100.03	0.00	05/14/2019	10:15
2	K2808-01DUP	RT-2683-RT-5156DUP	1	100.02	0.00	05/14/2019	10:25
3	K2836-02	CULVER-CBTC-WC1-0510	1	100.01	0.00	05/14/2019	10:32
4	K2837-01	SOIL-COMP	1	100.05	0.00	05/14/2019	10:40

WORKLIST(Hardcopy Internal Chain)

LB102727

WorkList Name : PF51419

WorkList ID : 126024

Date : 05-14-2019 09:15:25

Due Date	Matrix	Sample	Test	Preservative	Customer	Storage Location	Customer Sample	Collect Date	Method
05/10/2019	Solid	K2808-01	Paint Filter	Cool 4 deg C	PSEG01	K11	RT-2683-RT-5156	05/10/2019	9095B
05/10/2019	Solid	K2836-02	Paint Filter	Cool 4 deg C	DIST01	O52	CULVER-CBTC-WC1-051019	05/10/2019	9095B
05/13/2019	Solid	K2837-01	Paint Filter	Cool 4 deg C	PSEG01	O21	SOIL-COMP	05/13/2019	9095B

Date/Time 05/14/19 09:55
 Received by: KS
 Relinquished by: CP

Date/Time 05/14/19 10:45
 Received by: CP
 Relinquished by: KS