



Analytical Summary Report

Analysis Method: 9095B

Reviewed By: ketankumar

Parameter: Paint Filter

Supervisor Review By: apatel

Run Number: LB103029

BalanceID: WC SC-4

Seq	LabID	ClientID	Dilution	Weight(g)	Inst.Conc (ml/100g)	Anal Date	Anal Time
1	K3041-07	TP-2-S	1	100.03	0.00	05/28/2019	11:02
2	K3041-07DUP	TP-2-SDUP	1	100.02	0.00	05/28/2019	11:10
3	K3041-11	TP-2-D	1	100.01	0.00	05/28/2019	11:18
4	K3047-01	SOIL-COMP	1	100.07	0.00	05/28/2019	11:25
5	K3051-02	SP-1-A	1	100.06	0.00	05/28/2019	11:32
6	K3051-04	SP-2-B	1	100.05	0.00	05/28/2019	11:40
7	K3053-01	CR-SOIL-PILE	1	100.09	0.00	05/28/2019	11:48

WORKLIST(Hardcopy Internal Chain)

LB 103029

WorkList Name : PF52819

WorkList ID : 126616

Date : 05-28-2019 09:14:19

Due Date	Matrix	Sample	Test	Preservative	Customer	Storage Location	Customer Sample	Collect Date	Method
05/23/2019	Solid	K3041-07	Paint Filter	Cool 4 deg C	PSEG01	O21	TP-2-S	05/23/2019	9095B
05/23/2019	Solid	K3041-11	Paint Filter	Cool 4 deg C	PSEG01	O21	TP-2-D	05/23/2019	9095B
05/24/2019	Solid	K3047-01	Paint Filter	Cool 4 deg C	PSEG01	O11	SOIL-COMP	05/24/2019	9095B
05/24/2019	Solid	K3051-02	Paint Filter	Cool 4 deg C	PSEG01	O31	SP-1-A	05/24/2019	9095B
05/24/2019	Solid	K3051-04	Paint Filter	Cool 4 deg C	PSEG01	O31	SP-2-B	05/24/2019	9095B
05/24/2019	Solid	K3053-01	Paint Filter	Cool 4 deg C	PSEG01	O31	CR-SOIL-PILE	05/24/2019	9095B

Date/Time 05/28/19 10:45
 Received by: KS
 Relinquished by: JPB

Date/Time 05/28/19 11:55
 Received by: JPB
 Relinquished by: KS