



Analytical Summary Report

Analysis Method: 9095B

Reviewed By: ketankumar

Parameter: Paint Filter

Supervisor Review By: apatel

Run Number: LB103921

BalanceID: WC SC-4

Seq	LabID	ClientID	Dilution	Weight(g)	Inst.Conc (ml/100g)	Anal Date	Anal Time
1	K3621-01	OK-03-071019-A	1	100.03	0.00	07/11/2019	10:50
2	K3621-01DUP	OK-03-071019-ADUP	1	100.02	0.00	07/11/2019	10:58
3	K3621-03	OK-03-071019-B	1	100.01	0.00	07/11/2019	11:05
4	K3751-01	MANHOLE-TEST-PIT	1	100.07	0.00	07/11/2019	11:15
5	K3751-03	DUCT-BANK-TEST-PIT	1	100.04	0.00	07/11/2019	11:22

WORKLIST(Hardcopy Internal Chain)

LB 103921

WorkList Name : PF71119

WorkList ID : 128445

Department : Wet-Chemistry

Date : 07-11-2019 09:26:52

Due Date	Matrix	Sample	Test	Preservative	Customer	Storage Location	Customer Sample	Collect Date	Method
07/10/2019	Solid	K3621-01	Paint Filter	Cool 4 deg C	PSEG05	M32	OK-03-071019-A	07/10/2019	9095B
07/10/2019	Solid	K3621-03	Paint Filter	Cool 4 deg C	PSEG05	M32	OK-03-071019-B	07/10/2019	9095B
07/10/2019	Solid	K3751-01	Paint Filter	Cool 4 deg C	PSEG01	M31	MANHOLE-TEST-PIT	07/10/2019	9095B
07/10/2019	Solid	K3751-03	Paint Filter	Cool 4 deg C	PSEG01	M31	DUCT-BANK-TEST-PIT	07/10/2019	9095B

Date/Time 07/11/19 10:40
 Received by: KS
 Relinquished by: CP

Date/Time 07/11/19 11:25
 Received by: CP
 Relinquished by: KS