



Analytical Summary Report

Analysis Method: 9095B

Reviewed By: ketankumar

Parameter: Paint Filter

Supervisor Review By: AMANDEEP

Run Number: LB104186

BalanceID: WC SC-4

Seq	LabID	ClientID	Dilution	Weight(g)	Inst.Conc (ml/100g)	Anal Date	Anal Time
1	K3618-07	HD-02-072219	1	100.03	0.00	07/24/2019	11:30
2	K3618-07DUP	HD-02-072219DUP	1	100.02	0.00	07/24/2019	11:40
3	K3934-03	TP-2S	1	100.01	0.00	07/24/2019	11:48
4	K3934-07	TP-3S	1	100.07	0.00	07/24/2019	11:55
5	K3934-11	TP-1S	1	100.09	0.00	07/24/2019	12:05
6	K3936-01	SOIL-COMP	1	100.06	0.00	07/24/2019	12:12
7	K3943-01	PA-71619	1	100.04	0.00	07/24/2019	12:20

WORKLIST(Hardcopy Internal Chain)

LB104186

WorkList Name : PF72419 WorkList ID : 128966 Department : Wet-Chemistry Date : 07-24-2019 08:51:11

Due Date	Matrix	Sample	Test	Preservative	Customer	Storage Location	Customer Sample	Collect Date	Method
07/22/2019	Solid	K3618-07	Paint Filter	Cool 4 deg C	PSEG05		HD-02-072219	07/22/2019	9095B
07/19/2019	Solid	K3934-03	Paint Filter	Cool 4 deg C	PSEG01	M63	TP-2S	07/19/2019	9095B
07/19/2019	Solid	K3934-07	Paint Filter	Cool 4 deg C	PSEG01	M63	TP-3S	07/19/2019	9095B
07/19/2019	Solid	K3934-11	Paint Filter	Cool 4 deg C	PSEG01	M63	TP-1S	07/19/2019	9095B
07/22/2019	Solid	K3936-01	Paint Filter	Cool 4 deg C	PSEG01	M62	SOIL-COMP	07/22/2019	9095B
07/22/2019	Solid	K3943-01	Paint Filter	Cool 4 deg C	PSEG01	M61	PA-71619	07/22/2019	9095B

Date/Time 07/24/19 11:15
 Received by: KS
 Relinquished by: CP

Date/Time 07/24/19 12:25
 Received by: CP
 Relinquished by: KS