



Analytical Summary Report

Analysis Method: 9095B
Parameter: Paint Filter
Run Number: LB106655

Reviewed By: Daniel
Supervisor Review By: apatel
BalanceID: WC SC-4

Seq	LabID	ClientID	Dilution	Weight(g)	Inst.Conc (ml/100g)	Anal Date	Anal Time
1	K6111-01	CL-01-120619	1	100.03	0.00	12/09/2019	10:40
2	K6111-01DUP	CL-01-120619DUP	1	100.02	0.00	12/09/2019	10:48
3	K6117-01	TR-04-120619	1	100.05	0.00	12/09/2019	10:56
4	K6118-01	SU-02-120619	1	100.04	0.00	12/09/2019	11:06
5	K6188-01	SOIL-COMP-1	1	100.02	0.00	12/09/2019	11:12
6	K6188-05	SOIL-COMP-2	1	100.03	0.00	12/09/2019	11:22
7	K6194-02	WC-01	1	100.02	0.00	12/09/2019	11:30

WORKLIST(Hardcopy Internal Chain)

LB106655

WorkList Name : PF120919 WorkList ID : 133993 Department : Wet-Chemistry Date : 12-09-2019 10:03:40

Due Date	Matrix	Sample	Test	Preservative	Customer	Storage Location	Customer Sample	Collect Date	Method
12/06/2019	Solid	K6111-01	Paint Filter	Cool 4 deg C	PSEG05	H11	CL-01-120619	12/06/2019	9095B
12/06/2019	Solid	K6117-01	Paint Filter	Cool 4 deg C	PSEG05	H11	TR-04-120619	12/06/2019	9095B
12/06/2019	Solid	K6118-01	Paint Filter	Cool 4 deg C	PSEG05	H11	SU-02-120619	12/06/2019	9095B
12/06/2019	Solid	K6188-01	Paint Filter	Cool 4 deg C	PSEG01	H11	SOIL-COMP-1	12/06/2019	9095B
12/06/2019	Solid	K6188-05	Paint Filter	Cool 4 deg C	PSEG01	H11	SOIL-COMP-2	12/06/2019	9095B
12/06/2019	Solid	K6194-02	Paint Filter	Cool 4 deg C	AREC01	H61	WC-01	12/06/2019	9095B

Date/Time 12/09/19 10:35
 Received by: DK
 Relinquished by: SO

Date/Time 12/09/19 11:35
 Received by: SO
 Relinquished by: DK