



Analytical Summary Report

Analysis Method: 9095B

Reviewed By: Guerda

Parameter: Paint Filter

Supervisor Review By: Iwona

Run Number: LB120762

BalanceID:

Seq	LabID	ClientID	Dilution	Weight(g)	Inst.Conc (ml/100g)	Anal Date	Anal Time
1	N3364-01	OK-02-061522	1	100.05	0.00	06/20/2022	09:00
2	N3364-01DUP	OK-02-061522DUP	1	100.03	0.00	06/20/2022	09:08
3	N3371-01	VNJ-211	1	100.01	0.00	06/20/2022	09:15
4	N3390-01	PT-2-061722	1	100.06	0.00	06/20/2022	09:23
5	N3397-01	OR-2-061722	1	100.06	0.00	06/20/2022	09:30
6	N3414-01	SU-04-062022	1	100.02	0.00	06/20/2022	09:37

WORKLIST(Hardcopy Internal Chain)

LB120762

WorkList Name : PF-062022

WorkList ID : 160681

Department : Wet-Chemistry

Date : 06-20-2022 08:30:47

Due Date	Matrix	Sample	Test	Preservative	Customer	Raw Sample Storage Location	Customer Sample	Collect Date	Method
06/15/2022	Solid	N3364-01	Paint Filter	Cool 4 deg C	PSEG05	D11	OK-02-061522	06/15/2022	9095B
06/16/2022	Solid	N3371-01	Paint Filter	Cool 4 deg C	PSEG03	D11	VNJ-211	06/16/2022	9095B
06/17/2022	Solid	N3390-01	Paint Filter	Cool 4 deg C	PSEG03	D11	PT-2-061722	06/17/2022	9095B
06/17/2022	Solid	N3397-01	Paint Filter	Cool 4 deg C	PSEG05	N11	OR-2-061722	06/17/2022	9095B
06/20/2022	Solid	N3414-01	Paint Filter	Cool 4 deg C	PSEG05	D11	SU-04-062022	06/20/2022	9095B

Date/Time 6/20/22 8:40
 Raw Sample Received by: SM(wc)
 Raw Sample Relinquished by: ES(wc)

Date/Time 6/20/22 10:00
 Raw Sample Received by: ES(wc)
 Raw Sample Relinquished by: SM(wc)