



Analytical Summary Report

Analysis Method: 9095B
Parameter: Paint Filter
Run Number: LB127248

Reviewed By: Rubina
Supervisor Review By: Iwona
BalanceID: WC SC-4

Seq	LabID	ClientID	Dilution	Weight(g)	Inst.Conc (ml/100g)	Anal Date	Anal Time
1	O4392-01	WASTE	1	100.05	0.00	09/12/2023	14:10
2	O4392-01DUP	WASTEDUP	1	100.05	0.00	09/12/2023	14:17
3	O4393-01	WC-1	1	100.02	0.00	09/12/2023	14:25
4	O4395-01	OK-01-91123	1	100.06	0.00	09/12/2023	14:32
5	O4396-01	CHRT-24313	1	100.02	0.00	09/12/2023	14:40
6	O4401-01	MH110	1	100.06	0.00	09/12/2023	14:47
7	O4401-03	MH110	1	100.04	0.00	09/12/2023	14:55

WORKLIST(Hardcopy Internal Chain)

6127248

WorkList Name : pf 9-12 WorkList ID : 173491 Department : Wet-Chemistry Date : 09-12-2023 08:36:34

Sample	Customer Sample	Matrix	Test	Preservative	Customer	Raw Sample Storage Location	Collect Date	Method
O4392-01	WASTE	Solid	Paint Filter	Cool 4 deg C	RMJE02	N11	09/08/2023	9095B
O4393-01	WC-1	Solid	Paint Filter	Cool 4 deg C	PSEG03	N12	09/11/2023	9095B
O4395-01	OK-01-91123	Solid	Paint Filter	Cool 4 deg C	PSEG05	N11	09/11/2023	9095B
O4396-01	CHRT-24313	Solid	Paint Filter	Cool 4 deg C	PSEG03	N11	09/12/2023	9095B
O4401-01	MH110	Solid	Paint Filter	Cool 4 deg C	PSEG03	N11	09/11/2023	9095B
O4401-03	MH110	Solid	Paint Filter	Cool 4 deg C	PSEG03	N11	09/11/2023	9095B

Date/Time 09/12/2023 14:00
 Raw Sample Received by: RMC CWC
 Raw Sample Relinquished by: RMC CWC

Date/Time 09/12/2023 15:10
 Raw Sample Received by: RMC CWC
 Raw Sample Relinquished by: RMC CWC