

Analytical Summary Report

Analysis Method: 9095A Reviewed By: ketankumar

Parameter: Paint Filter Supervisor Review By: apatel

Run Number: LB86746 BalanceID: $\[MC\]$ SC-4

| Seq | LabID | ClientID | Dilution | Weight(g) | Inst. Conc (ml/100g) | Anal Date | Anal Time |
|-----|-------------|----------|----------|-----------|-------------------------|------------|-----------|
| 1 | 12577-01 | WASTE | 1 | 100.03 | 0.00 | 04/06/2017 | 17:10 |
| 2 | I2577-01DUP | WASTEDUP | 1 | 100.02 | 0.00 | 04/06/2017 | 17:22 |

WORKLIST(Hardcopy Internal Chain)

1B86746

WorkList Name: PF4617-1

Due Date

Matrix

Sample

Test

Solid

12577-01

Paint Filter

Cool 4 deg C

RMJE02

N21

WASTE

04/06/2017

9095A

Preservative

Customer

Storage Location

Customer Sample

Collect Date

Method

WorkList ID:

97209

Date:

4/6/2017 4:57:01 PM

Received by: Date/Time

Relinquished by:

Relinquished by: Received by: Date/Time

Page 1 of 1