



Analytical Summary Report

Analysis Method: 9095A

Reviewed By: ketankumar

Parameter: Paint Filter

Supervisor Review By: apatel

Run Number: LB87111

BalanceID: WC SC-4

Seq	LabID	ClientID	Dilution	Weight(g)	Inst. Conc (ml/100g)	Anal Date	Anal Time
1	I2869-01	KEARNY-GEN-STA-SP- (0	1	100.02	0.00	04/27/2017	16:15
2	I2869-01DUP	KEARNY-GEN-STA-SP- (0	1	100.03	0.00	04/27/2017	16:25
3	I2870-01	SOIL-CUTTINGS-DRUMS	1	100.03	0.00	04/27/2017	16:40
4	I2873-02	MANHOLE-9-COMP	1	100.04	0.00	04/27/2017	16:55

WORKLIST(Hardcopy Internal Chain)

LB87111

WorkList Name : PF42717

WorkList ID : 97845

Date : 4/27/2017 3:45:01 PM

Due Date	Matrix	Sample	Test	Preservative	Customer	Storage Location	Customer Sample	Collect Date	Method
04/26/2017	Solid	I2869-01	Paint Filter	Cool 4 deg C	PSEG01	D11	KEARNY-GEN-STA-SP-(0-2)	04/26/2017	9095A
	Solid	I2870-01	Paint Filter	Cool 4 deg C	PSEG01	D12	SOIL-CUTTINGS-DRUMS(CC	04/26/2017	9095A
04/27/2017	Solid	I2873-02	Paint Filter	Cool 4 deg C	PSEG01	P63	MANHOLE-9-COMP	04/27/2017	9095A

Date/Time

4/27/17 4:00 PM

Received by:

KS

Relinquished by:

CS

Date/Time

4/27/17 17:00

Received by:

CS

Relinquished by:

KS