



Analytical Summary Report

Analysis Method: 9095A

Reviewed By: ketankumar

Parameter: Paint Filter

Supervisor Review By: apatel

Run Number: LB88235

BalanceID: WC SC-4

Seq	LabID	ClientID	Dilution	Weight(g)	Inst. Conc (ml/100g)	Anal Date	Anal Time
1	I3762-01	SA-RO-0033-061617	1	100.03	0.00	06/20/2017	10:45
2	I3762-01DUP	SA-RO-0033-061617DUP	1	100.02	0.00	06/20/2017	10:55
3	I3781-03	SB-09-COMP	1	100.04	0.00	06/20/2017	11:10
4	I3781-05	SB-01-COMP	1	100.03	0.00	06/20/2017	11:20

WORKLIST(Hardcopy Internal Chain)

LB 88235

Worklist Name : PF62017

Worklist ID : 99798

Date : 6/20/2017 8:54:11 AM

Due Date	Matrix	Sample	Test	Preservative	Customer	Storage Location	Customer Sample	Collect Date	Method
06/16/2017	Solid	13762-01	Paint Filter	Cool 4 deg C	PSEG05	N61	SA-RO-0033-061617	06/16/2017	9095A
	Solid	13781-03	Paint Filter	Cool 4 deg C	LIR001	M42	SB-09-COMP	06/19/2017	9095A
	Solid	13781-05	Paint Filter	Cool 4 deg C	LIR001	M42	SB-01-COMP	06/19/2017	9095A

Date/Time

06/20/17 10:20 AM

Received by:

KS

Relinquished by:

CS

Date/Time

06/20/17 11:25 AM

Received by:

CS

Relinquished by:

KS