



Analytical Summary Report

Analysis Method: 9095A

Reviewed By: ketankumar

Parameter: Paint Filter

Supervisor Review By: apatel

Run Number: LB89631

BalanceID: WC SC-4

Seq	LabID	ClientID	Dilution	Weight(g)	Inst. Conc (ml/100g)	Anal Date	Anal Time
1	I4892-01	HR-06-081817	1	100.03	0.00	08/21/2017	14:02
2	I4892-01DUP	HR-06-081817DUP	1	100.02	0.00	08/21/2017	14:12
3	I4898-01	NB-08-081817-A	1	100.04	0.00	08/21/2017	14:20
4	I4898-04	NB-08-081817-B	1	100.04	0.00	08/21/2017	14:28
5	I4900-15	220-1-STONE	1	100.02	0.00	08/21/2017	14:35
6	I4900-17	220-2-STONE	1	100.02	0.00	08/21/2017	14:42

WORKLIST(Hardcopy Internal Chain)

WorkList Name : PF82117

WorkList ID : 102123

Date : 8/21/2017 9:03:45 AM

Due Date	Matrix	Sample	Test	Preservative	Customer	Storage Location	Customer Sample	Collect Date	Method
08/18/2017	Solid	I4892-01	Paint Filter	Cool 4 deg C	PSEG05	N11	HR-06-081817	08/18/2017	9095A
08/18/2017	Solid	I4898-01	Paint Filter	Cool 4 deg C	PSEG05	N11	NB-08-081817-A	08/18/2017	9095A
08/18/2017	Solid	I4898-04	Paint Filter	Cool 4 deg C	PSEG05	N11	NB-08-081817-B	08/18/2017	9095A
08/18/2017	Solid	I4900-15	Paint Filter	Cool 4 deg C	PSEG01	M43	220-1-STONE	08/18/2017	9095A
08/18/2017	Solid	I4900-17	Paint Filter	Cool 4 deg C	PSEG01	M43	220-2-STONE	08/18/2017	9095A

Date/Time

Received by:

Relinquished by:

08/21/17 9:15 AM
KS
CP

Date/Time

Received by:

Relinquished by:

08/21/17 14:50
CP
KS

LB89631