



## Analytical Summary Report

Analysis Method: 9095A

Reviewed By: HIRAL

Parameter: Paint Filter

Supervisor Review By: apatel

Run Number: LB92074

BalanceID: WC SC-4

| Seq | LabID       | ClientID         | Dilution | Weight(g) | Inst. Conc<br>(ml/100g) | Anal Date  | Anal Time |
|-----|-------------|------------------|----------|-----------|-------------------------|------------|-----------|
| 1   | I6813-01    | Soil-Cuttings    | 1        | 100.03    | 0.00                    | 12/11/2017 | 09:24     |
| 2   | I6813-01DUP | Soil-CuttingsDUP | 1        | 100.01    | 0.00                    | 12/11/2017 | 09:32     |
| 3   | I6814-01    | PHMHC-WC1        | 1        | 100.04    | 0.00                    | 12/11/2017 | 09:40     |

# WORKLIST(Hardcopy Internal Chain)

LB 92074

WorkList Name : PF121117

WorkList ID : 106368

Date : 12/11/2017 9:08:27 AM

| Due Date   | Matrix | Sample   | Test         | Preservative | Customer | Storage Location | Customer Sample | Collect Date | Method |
|------------|--------|----------|--------------|--------------|----------|------------------|-----------------|--------------|--------|
| 12/08/2017 | Solid  | 16813-01 | Paint Filter | Cool 4 deg C | PSEG01   | M52              | Soil-Cuttings   | 12/08/2017   | 9095A  |
| 12/08/2017 | Solid  | 16814-01 | Paint Filter | Cool 4 deg C | DEWB01   | P33              | PHMHC-WC1       | 12/08/2017   | 9095A  |

Date/Time 12/11/17 9:15  
 Received by: HP  
 Relinquished by: CP

Date/Time 12/11/17 09:45  
 Received by: CP  
 Relinquished by: HP