



Analytical Summary Report

Analysis Method: 9095A

Reviewed By: Hiral

Parameter: Paint Filter

Supervisor Review By: KETANKUMAR

Run Number: LB93696

BalanceID: WC SC-4

Seq	LabID	ClientID	Dilution	Weight(g)	Inst. Conc (ml/100g)	Anal Date	Anal Time
1	J1761-01	TR-04-0302018	1	100.02	0.00	03/05/2018	11:03
2	J1761-01DUP	TR-04-0302018DUP	1	100.03	0.00	03/05/2018	11:10
3	J1783-01	SLUDGE	1	100.04	0.00	03/05/2018	11:17
4	J1792-01	TP-6	1	100.05	0.00	03/05/2018	11:24
5	J1792-03	TP-7	1	100.01	0.00	03/05/2018	11:31
6	J1792-05	TP-8	1	100.06	0.00	03/05/2018	11:38
7	J1792-07	TP-12	1	100.03	0.00	03/05/2018	11:45
8	J1792-09	TP-13	1	100.04	0.00	03/05/2018	11:52

WORKLIST(Hardcopy Internal Chain)

LB 93696

Worklist Name : PF3518

Worklist ID : 109245

Date : 3/5/2018 8:09:45 AM

Due Date	Matrix	Sample	Test	Preservative	Customer	Storage Location	Customer Sample	Collect Date	Method
03/02/2018	Solid	J1761-01	Paint Filter	Cool 4 deg C	PSEG05	G32	TR-04-0302018	03/02/2018	9095A
03/02/2018	Solid	J1783-01	Paint Filter	Cool 4 deg C	PSEG01	G31	SLUDGE	03/02/2018	9095A
03/01/2018	Solid	J1792-01	Paint Filter	Cool 4 deg C	PSEG01	G32	TP-6	03/01/2018	9095A
03/01/2018	Solid	J1792-03	Paint Filter	Cool 4 deg C	PSEG01	G32	TP-7	03/01/2018	9095A
03/01/2018	Solid	J1792-05	Paint Filter	Cool 4 deg C	PSEG01	G32	TP-8	03/01/2018	9095A
03/01/2018	Solid	J1792-07	Paint Filter	Cool 4 deg C	PSEG01	G32	TP-12	03/01/2018	9095A
03/01/2018	Solid	J1792-09	Paint Filter	Cool 4 deg C	PSEG01	G32	TP-13	03/01/2018	9095A

Date/Time

3/5/18 10:55

Received by:

HP

Relinquished by:

HP

Date/Time

3/5/18 12:00

Received by:

HP

Relinquished by:

HP