



Analytical Summary Report

Analysis Method: 9095A

Reviewed By: Hiral

Parameter: Paint Filter

Supervisor Review By: KETANKUMAR

Run Number: LB93715

BalanceID: WC SC-4

Seq	LabID	ClientID	Dilution	Weight(g)	Inst. Conc (ml/100g)	Anal Date	Anal Time
1	J1731-04	BALER-SOIL	1	100.03	0.00	03/06/2018	10:48
2	J1731-04DUP	BALER-SOILDUP	1	100.02	0.00	03/06/2018	10:55
3	J1809-01	RO-1-4	1	100.01	0.00	03/06/2018	11:02
4	J1809-05	RO-5-7	1	100.04	0.00	03/06/2018	11:09
5	J1810-01	MHA-WCS	1	100.06	0.00	03/06/2018	11:16
6	J1810-03	MHA-WCD	1	100.05	0.00	03/06/2018	11:23

WORKLIST(Hardcopy Internal Chain)

LB 93715

Worklist Name : PF3618

Worklist ID : 109289

Date : 3/6/2018 8:16:49 AM

Due Date	Matrix	Sample	Test	Preservative	Customer	Storage Location	Customer Sample	Collect Date	Method
03/05/2018	Solid	J1731-04 A	Paint Filter	Cool 4 deg C	PSEG02	I11	BALER-SOIL	03/05/2018	9095A
03/05/2018	Solid	J1809-01 B	Paint Filter	Cool 4 deg C	PSEG01	I12	RO-1-4	03/05/2018	9095A
03/05/2018	Solid	J1809-05 C	Paint Filter	Cool 4 deg C	PSEG01	I12	RO-5-7	03/05/2018	9095A
03/05/2018	Solid	J1810-01 G	Paint Filter	Cool 4 deg C	PSEG01	I13	MHA-WCS	03/05/2018	9095A
03/05/2018	Solid	J1810-03 P	Paint Filter	Cool 4 deg C	PSEG01	I13	MHA-WCD	03/05/2018	9095A

Date/Time 3/6/18 10:40

Received by: HP

Relinquished by:

Date/Time 3/6/18 11:30

Received by: HP

Relinquished by: