



Analytical Summary Report

Analysis Method: 1010A

Reviewed By: HIRAL

Parameter: Flash Point

Supervisor Review By: KETANKUMAR

Run Number: LB93747

Ambient Barometric Pressure (mmHg): 760

Reagent/Standard	Lot/Log #
p-xylene (ICV)	W2168

Seq	LabID	True Value °F	Dilution	Celsius °C	Result °F	Anal Date	Anal Time
1	ICV	81	1	27.0	80.6	03/08/2018	09:10
2	J1814-01		1	>100.0	>212.0	03/08/2018	09:40
3	J1814-01DUP		1	>100.0	>212.0	03/08/2018	10:10
4	J1819-08		1	>100.0	>212.0	03/08/2018	10:35

Result = (Celsius * 1.8) + 32

WORKLIST(Hardcopy Internal Chain)

LB 93747

WorkList Name : FP3818

WorkList ID : 109351

Date : 3/8/2018 8:21:08 AM

Due Date	Matrix	Sample	Test	Preservative	Customer	Storage Location	Customer Sample	Collect Date	Method
03/09/2018	Water	J1814-01	Flash Point	Cool 4 deg C	TULL01	H33	DREDGE-DECANT-WATER	03/05/2018	1010A
03/09/2018	Water	J1819-08	Flash Point	Cool 4 deg C	PSEG01	I13	TP-10	03/05/2018	1010A

Date/Time 3/8/18 8:30 AM
 Received by: KS
 Relinquished by: CP

Date/Time 3/8/18 10:40 AM
 Received by: CP
 Relinquished by: KS