



Analytical Summary Report

Analysis Method: 9095A

Reviewed By: Hiral

Parameter: Paint Filter

Supervisor Review By: ketankumar

Run Number: LB94334

BalanceID: WC SC-4

Seq	LabID	ClientID	Dilution	Weight(g)	Inst. Conc (ml/100g)	Anal Date	Anal Time
1	J2185-01	LOWER-CONCRETE-SLAB	1	100.04	0.00	04/03/2018	09:53
2	J2185-01DUP	LOWER-CONCRETE-SLAB	1	100.01	0.00	04/03/2018	10:00
3	J2185-10	LOWER-CONCRETE-SLAB	1	100.02	0.00	04/03/2018	10:06

WORKLIST(Hardcopy Internal Chain)

LB94334

WorkList Name : PF4318

WorkList ID : 110342

Date : 4/3/2018 8:10:27 AM

Due Date	Matrix	Sample	Test	Preservative	Customer	Storage Location	Customer Sample	Collect Date	Method
04/02/2018	Solid	J2185-01	Paint Filter	Cool 4 deg C	PSEG01	L31	LOWER-CONCRETE-SLAB-1	04/02/2018	9095A
04/02/2018	Solid	J2185-10	Paint Filter	Cool 4 deg C	PSEG01	L31	LOWER-CONCRETE-SLAB-2	04/02/2018	9095A

Date/Time 4/3/18 9:45
 Received by: HP
 Relinquished by: [Signature]

Date/Time 4/3/18 10:10
 Received by: [Signature]
 Relinquished by: HP