



Analytical Summary Report

Analysis Method: 9095A

Reviewed By: Hiral

Parameter: Paint Filter

Supervisor Review By: KETANKUMAR

Run Number: LB94697

BalanceID: WC SC-4

Seq	LabID	ClientID	Dilution	Weight(g)	Inst. Conc (ml/100g)	Anal Date	Anal Time
1	J2423-01	NYS-RBR200034	1	100.03	0.00	04/18/2018	09:02
2	J2423-01DUP	NYS-RBR200034DUP	1	100.02	0.00	04/18/2018	09:09
3	J2423-04	NYS-RBR200035	1	100.01	0.00	04/18/2018	09:16
4	J2425-01	T-3	1	100.05	0.00	04/18/2018	09:22
5	J2427-01	T-2	1	100.02	0.00	04/18/2018	09:29
6	J2428-01	TP-1-TP-2	1	100.06	0.00	04/18/2018	09:36

WORKLIST(Hardcopy Internal Chain)

LB94697

Worklist Name : PF-041818

Worklist ID : 110918

Date : 4/18/2018 8:12:25 AM

Due Date	Matrix	Sample	Test	Preservative	Customer	Storage Location	Customer Sample	Collect Date	Method
04/17/2018	Solid	J2423-01	✓ Paint Filter	Cool 4 deg C	PSEG01	G11	NYS-RBR200034	04/17/2018	9095A
04/17/2018	Solid	J2423-04	✓ Paint Filter	Cool 4 deg C	PSEG01	G11	NYS-RBR200035	04/17/2018	9095A
04/17/2018	Solid	J2425-01	✓ Paint Filter	Cool 4 deg C	PSEG01	G21	TP-3	04/17/2018	9095A
04/17/2018	Solid	J2427-01	✓ Paint Filter	Cool 4 deg C	PSEG01	G21	TP-2	04/17/2018	9095A
04/17/2018	Solid	J2428-01	✓ Paint Filter	Cool 4 deg C	PSEG01	G12	TP-1-TP-2	04/17/2018	9095A

Date/Time 4/18/18 8:55
 Received by: HP
 Relinquished by: CP

Date/Time 4/18/18 9:40
 Received by: CP
 Relinquished by: HP