



Analytical Summary Report

Analysis Method: 9095A

Reviewed By: Hiral

Parameter: Paint Filter

Supervisor Review By: ketankumar

Run Number: LB95048

BalanceID: WC SC-4

Seq	LabID	ClientID	Dilution	Weight(g)	Inst. Conc (ml/100g)	Anal Date	Anal Time
1	J2665-01	ES-RO-124030	1	100.03	0.00	05/02/2018	10:32
2	J2665-01DUP	ES-RO-124030DUP	1	100.01	0.00	05/02/2018	10:39
3	J2665-05	ES-RT-2655	1	100.04	0.00	05/02/2018	10:45
4	J2665-09	ES-RT-1871	1	100.06	0.00	05/02/2018	10:52
5	J2667-02	285-147-7212002-RB2	1	100.02	0.00	05/02/2018	10:59
6	J2667-05	155-348-281	1	100.01	0.00	05/02/2018	11:06
7	J2667-08	137-132-165	1	100.05	0.00	05/02/2018	11:13

WORKLIST(Hardcopy Internal Chain)

LB 95048

WorkList Name : PF-050218

WorkList ID : 111529

Date : 5/2/2018 8:17:05 AM

Due Date	Matrix	Sample	Test	Preservative	Customer	Storage Location	Customer Sample	Collect Date	Method
05/01/2018	Solid	J2665-01	H Paint Filter	Cool 4 deg C	PSEG01	B62	ES-RO-124030	05/01/2018	9095A
05/01/2018	Solid	J2665-05	H Paint Filter	Cool 4 deg C	PSEG01	B62	ES-RT-2655	05/01/2018	9095A
05/01/2018	Solid	J2665-09	H Paint Filter	Cool 4 deg C	PSEG01	B62	ES-RT-1871	05/01/2018	9095A
05/01/2018	Solid	J2667-02	B Paint Filter	Cool 4 deg C	PSEG01	B63	285-147-7212002-RB26667	05/01/2018	9095A
05/01/2018	Solid	J2667-05	B Paint Filter	Cool 4 deg C	PSEG01	B63	155-348-281	05/01/2018	9095A
05/01/2018	Solid	J2667-08	A Paint Filter	Cool 4 deg C	PSEG01	B63	137-132-165	05/01/2018	9095A

Date/Time 05/02/18 10:25

Received by: HP

Relinquished by: CP

Date/Time 05/02/18 11:20

Received by: CP

Relinquished by: HP