



Analytical Summary Report

Analysis Method: 9095A

Reviewed By: Hiral

Parameter: Paint Filter

Supervisor Review By: KETANKUMAR

Run Number: LB95569

BalanceID: WC SC-4

Seq	LabID	ClientID	Dilution	Weight(g)	Inst. Conc (ml/100g)	Anal Date	Anal Time
1	J2669-09	SU-02-052218	1	100.02	0.00	05/23/2018	10:32
2	J2669-09DUP	SU-02-052218DUP	1	100.03	0.00	05/23/2018	10:39
3	J3060-01	TP-3-WC-1	1	100.01	0.00	05/23/2018	10:45
4	J3060-03	TP-3-WC-2	1	100.05	0.00	05/23/2018	10:51
5	J3060-05	TP-3-WC-3	1	100.06	0.00	05/23/2018	10:57
6	J3075-01	RO-4-1	1	100.04	0.00	05/23/2018	11:04

WORKLIST(Hardcopy Internal Chain)

LB95569

WorkList Name : PF-052318

WorkList ID : 112472

Date : 5/23/2018 8:06:11 AM

Due Date	Matrix	Sample	Test	Preservative	Customer	Storage Location	Customer Sample	Collect Date	Method
05/22/2018	Solid	J2669-09	Paint Filter	Cool 4 deg C	PSEG05		SU-02-052218	05/22/2018	9095A
05/21/2018	Solid	J3060-01	Paint Filter	Cool 4 deg C	PSEG01	I32	TP-3-WC-1	05/21/2018	9095A
05/21/2018	Solid	J3060-03	Paint Filter	Cool 4 deg C	PSEG01	I32	TP-3-WC-2	05/21/2018	9095A
05/21/2018	Solid	J3060-05	Paint Filter	Cool 4 deg C	PSEG01	I32	TP-3-WC-3	05/21/2018	9095A
05/22/2018	Solid	J3075-01	Paint Filter	Cool 4 deg C	PSEG01	H32	RO-4-1	05/22/2018	9095A

Date/Time

5/23/18 10:25

Received by:

HP

Relinquished by:

Q

Date/Time

5/23/18 11:10

Received by:

Q

Relinquished by:

HP