



Analytical Summary Report

Analysis Method: 9095A

Reviewed By: Hiral

Parameter: Paint Filter

Supervisor Review By: KETANKUMAR

Run Number: LB95877

BalanceID: WC SC-4

Seq	LabID	ClientID	Dilution	Weight(g)	Inst. Conc (ml/100g)	Anal Date	Anal Time
1	J3252-01	TR-04-060618	1	100.02	0.00	06/07/2018	09:37
2	J3252-01DUP	TR-04-060618DUP	1	100.05	0.00	06/07/2018	09:43
3	J3344-01	HS-YARD-1	1	100.01	0.00	06/07/2018	09:49
4	J3344-05	HS-YARD-2	1	100.04	0.00	06/07/2018	09:55
5	J3344-09	HS-HOUSE-WALL	1	100.03	0.00	06/07/2018	10:01
6	J3352-01	PS-SOIL	1	100.02	0.00	06/07/2018	10:06

WORKLIST(Hardcopy Internal Chain)

LB95877

Worklist Name : PF-060718

Worklist ID : 113054

Date : 6/7/2018 7:57:29 AM

Due Date	Matrix	Sample	Test	Preservative	Customer	Storage Location	Customer Sample	Collect Date	Method
06/06/2018	Solid	J3252-01	H Paint Filter	Cool 4 deg C	PSEG05	I63	TR-04-060618	06/06/2018	9095A
06/06/2018	Solid	J3344-01	✓ Paint Filter	Cool 4 deg C	PSEG01	I63	HS-YARD-1	06/06/2018	9095A
06/06/2018	Solid	J3344-05	✓ Paint Filter	Cool 4 deg C	PSEG01	I63	HS-YARD-2	06/06/2018	9095A
06/06/2018	Solid	J3344-09	✓ Paint Filter	Cool 4 deg C	PSEG01	I63	HS-HOUSE-WALL	06/06/2018	9095A
06/06/2018	Solid	J3352-01	F Paint Filter	Cool 4 deg C	PSEG01	I63	PS-SOIL	06/06/2018	9095A

Date/Time 6/7/18 9:36
 Received by: HP
 Relinquished by: CP

Date/Time 6/7/18 10:10
 Received by: CP
 Relinquished by: HP