



Analytical Summary Report

Analysis Method: 9095A
Parameter: Paint Filter
Run Number: LB96853

Reviewed By: sweta
Supervisor Review By: ketankumar
BalanceID: WC SC-4

Seq	LabID	ClientID	Dilution	Weight(g)	Inst. Conc (ml/100g)	Anal Date	Anal Time
1	J3821-07	HR-06-072418-A	1	100.01	0.00	07/25/2018	14:10
2	J3821-07DUP	HR-06-072418-ADUP	1	100.02	0.00	07/25/2018	14:20
3	J3821-09	HR-06-072418-B	1	100.02	0.00	07/25/2018	14:30
4	J3821-11	HR-06-072418-C	1	100.03	0.00	07/25/2018	14:40
5	J4123-01	RO-1-3	1	100.01	0.00	07/25/2018	14:55
6	J4124-03	TP-11-S	1	100.02	0.00	07/25/2018	15:05
7	J4124-07	TP-11-D	1	100.01	0.00	07/25/2018	15:15

WORKLIST(Hardcopy Internal Chain)

LB 96853

WorkList Name : PF072518

WorkList ID : 114851

Date : 7/25/2018 8:52:53 AM

Due Date	Matrix	Sample	Test	Preservative	Customer	Storage Location	Customer Sample	Collect Date	Method
07/24/2018	Solid	J3821-07	B Paint Filter	Cool 4 deg C	PSEG05		HR-06-072418-A	07/24/2018	9095A
07/24/2018	Solid	J3821-09	B Paint Filter	Cool 4 deg C	PSEG05		HR-06-072418-B	07/24/2018	9095A
07/24/2018	Solid	J3821-11	A Paint Filter	Cool 4 deg C	PSEG05		HR-06-072418-C	07/24/2018	9095A
07/24/2018	Solid	J4123-01	B Paint Filter	Cool 4 deg C	PSEG01	K63	RO-1-3	07/24/2018	9095A
07/24/2018	Solid	J4124-03	✓ Paint Filter	Cool 4 deg C	PSEG01	K63	TP-11-S	07/24/2018	9095A
07/24/2018	Solid	J4124-07	C Paint Filter	Cool 4 deg C	PSEG01	K63	TP-11-D	07/24/2018	9095A

Date/Time 07/25/18 11:45

Received by: SP

Relinquished by: SP

Date/Time 07/25/18 3:30

Received by: SP

Relinquished by: SP