



Analytical Summary Report

Analysis Method: 9095A

Reviewed By: sweta

Parameter: Paint Filter

Supervisor Review By: ketankumar

Run Number: LB96969

BalanceID: WC SC-4

Seq	LabID	ClientID	Dilution	Weight(g)	Inst. Conc (ml/100g)	Anal Date	Anal Time
1	J3831-03	SU-03-072718	1	100.01	0.00	07/30/2018	12:20
2	J3831-03DUP	SU-03-072718DUP	1	100.02	0.00	07/30/2018	12:30
3	J4217-01	SOIL-1	1	100.02	0.00	07/30/2018	12:40
4	J4217-05	SOIL-2	1	100.02	0.00	07/30/2018	12:55
5	J4218-03	TP-15-S	1	100.03	0.00	07/30/2018	13:05
6	J4218-07	TP-15-D	1	100.01	0.00	07/30/2018	13:15

WORKLIST(Hardcopy Internal Chain)

LB 96969

WorkList Name : PF073018

WorkList ID : 115034

Date : 7/30/2018 8:16:09 AM

Due Date	Matrix	Sample	Test	Preservative	Customer	Storage Location	Customer Sample	Collect Date	Method
07/27/2018	Solid	J3831-03	I Paint Filter	Cool 4 deg C	PSEG05		SU-03-072718	07/27/2018	9095A
07/27/2018	Solid	J4217-01	F Paint Filter	Cool 4 deg C	PSEG01	K63	SOIL-1	07/27/2018	9095A
07/27/2018	Solid	J4217-05	Cx Paint Filter	Cool 4 deg C	PSEG01	K63	SOIL-2	07/27/2018	9095A
07/27/2018	Solid	J4218-03	E Paint Filter	Cool 4 deg C	PSEG01	K63	TP-15-S	07/27/2018	9095A
07/27/2018	Solid	J4218-07	E Paint Filter	Cool 4 deg C	PSEG01	K63	TP-15-D	07/27/2018	9095A

Date/Time 07/30/18 10:20
 Received by: SP
 Relinquished by: CP

Date/Time 07/30/18 13:20
 Received by: CP
 Relinquished by: SP