



Analytical Summary Report

Analysis Method: 9095B

Reviewed By: sweta

Parameter: Paint Filter

Supervisor Review By: ketankumar

Run Number: LB98636

BalanceID: WC SC-4

Seq	LabID	ClientID	Dilution	Weight(g)	Inst. Conc (ml/100g)	Anal Date	Anal Time
1	J5524-01	BS-SOIL-1	1	100.03	0.00	10/16/2018	11:20
2	J5524-01DUP	BS-SOIL-1DUP	1	100.02	0.00	10/16/2018	11:25
3	J5524-05	BS-SOIL-2	1	100.03	0.00	10/16/2018	11:30
4	J5527-01	SP-STONE	1	100.01	0.00	10/16/2018	11:35

LB98636

WORKLIST(Hardcopy Internal Chain)

WorkList Name : PF101618

WorkList ID : 118076

Date : 10/16/2018 10:43:33 AM

Due Date	Matrix	Sample	Test	Preservative	Customer	Storage Location	Customer Sample	Collect Date	Method
10/15/2018	Solid	J5524-01 <i>E</i>	Paint Filter	Cool 4 deg C	PSEG01	P31	BS-SOIL-1	10/15/2018	9095B
10/15/2018	Solid	J5524-05 <i>F</i>	Paint Filter	Cool 4 deg C	PSEG01	P31	BS-SOIL-2	10/15/2018	9095B
10/15/2018	Solid	J5527-01 <i>D</i>	Paint Filter	Cool 4 deg C	PSEG01	P31	SP-STONE	10/15/2018	9095B

Date/Time 10/16/18 11:20

Received by: *SP*Relinquished by: *SP*

Date/Time 10/16/18 11:20

Received by: *SP*Relinquished by: *SP*