



Analytical Summary Report

Analysis Method: 9095B

Reviewed By: sweta

Parameter: Paint Filter

Supervisor Review By: ketankumar

Run Number: LB98758

BalanceID: WC SC-4

Seq	LabID	ClientID	Dilution	Weight(g)	Inst. Conc (ml/100g)	Anal Date	Anal Time
1	J5197-03	HD-02-101918	1	100.02	0.00	10/22/2018	11:30
2	J5197-03DUP	HD-02-101918DUP	1	100.03	0.00	10/22/2018	11:35
3	J5604-01	MS-VB-29736-BOX-2	1	100.02	0.00	10/22/2018	11:40
4	J5604-03	MS-VB-25868-BOX-1	1	100.01	0.00	10/22/2018	11:45
5	J5605-01	TP-A	1	100.03	0.00	10/22/2018	11:50
6	J5605-07	TP-B	1	100.03	0.00	10/22/2018	11:55
7	J5606-01	SOIL-PILE	1	100.01	0.00	10/22/2018	12:00

WORKLIST(Hardcopy Internal Chain)

98758

WorkList Name : PF102218

WorkList ID : 118313

Date : 10/22/2018 11:19:47 AM

Due Date	Matrix	Sample	Test	Preservative	Customer	Storage Location	Customer Sample	Collect Date	Method
10/19/2018	Solid	J5197-03	Paint Filter	Cool 4 deg C	PSEG05	E22	HD-02-101918	10/19/2018	9095B
10/19/2018	Solid	J5604-01	Paint Filter	Cool 4 deg C	PSEG01	E22	MS-VB-29736-BOX-2	10/19/2018	9095B
10/19/2018	Solid	J5604-03	Paint Filter	Cool 4 deg C	PSEG01	E22	MS-VB-25868-BOX-1	10/19/2018	9095B
10/19/2018	Solid	J5605-01	Paint Filter	Cool 4 deg C	PSEG01	E22	TP-A	10/19/2018	9095B
10/19/2018	Solid	J5605-07	Paint Filter	Cool 4 deg C	PSEG01	E22	TP-B	10/19/2018	9095B
10/19/2018	Solid	J5606-01	Paint Filter	Cool 4 deg C	PSEG01	E22	SOIL-PILE	10/19/2018	9095B

Date/Time 10/22/18 11:20
 Received by: SP
 Relinquished by: CP

Date/Time 10/22/18 12:05
 Received by: CP
 Relinquished by: SP