



Analytical Summary Report

Analysis Method: 9095B

Reviewed By: ketankumar

Parameter: Paint Filter

Supervisor Review By: sweta

Run Number: LB99756

BalanceID: WC SC-4

Seq	LabID	ClientID	Dilution	Weight(g)	Inst. Conc (ml/100g)	Anal Date	Anal Time
1	J6189-01	HR-05-121118-A	1	100.05	0.00	12/12/2018	11:20
2	J6189-01DUP	HR-05-121118-ADUP	1	100.04	0.00	12/12/2018	11:32
3	J6189-03	HR-05-121118-B	1	100.06	0.00	12/12/2018	11:40
4	J6189-05	HR-05-121118-C	1	100.07	0.00	12/12/2018	11:48
5	J6194-05	OK-03-121118	1	100.08	0.00	12/12/2018	12:10
6	J6344-01	RBR-200027	1	100.05	0.00	12/12/2018	12:20
7	J6344-04	RBR-200031	1	100.06	0.00	12/12/2018	12:30
8	J6354-01	SOIL	1	100.05	0.00	12/12/2018	12:42

WORKLIST(Hardcopy Internal Chain)

LB99756

WorkList Name : pf121218

WorkList ID : 120259

Date : 12/12/2018 10:42:34 AM

Due Date	Matrix	Sample	Test	Preservative	Customer	Storage Location	Customer Sample	Collect Date	Method
12/11/2018	Solid	J6189-01	Paint Filter	Cool 4 deg C	PSEG05	D11	HR-05-121118-A	12/11/2018	9095B
12/11/2018	Solid	J6189-03	Paint Filter	Cool 4 deg C	PSEG05	D11	HR-05-121118-B	12/11/2018	9095B
12/11/2018	Solid	J6189-05	Paint Filter	Cool 4 deg C	PSEG05	D11	HR-05-121118-C	12/11/2018	9095B
12/11/2018	Solid	J6194-05	Paint Filter	Cool 4 deg C	PSEG05		OK-03-121118	12/11/2018	9095B
12/11/2018	Solid	J6344-01	Paint Filter	Cool 4 deg C	PSEG01	D11	RBR-200027	12/11/2018	9095B
12/11/2018	Solid	J6344-04	Paint Filter	Cool 4 deg C	PSEG01	D11	RBR-200031	12/11/2018	9095B
12/11/2018	Solid	J6354-01	Paint Filter	Cool 4 deg C	PSEG01	D12	SOIL	12/11/2018	9095B

Date/Time 12/12/18 10:45 AM

Received by: KS

Relinquished by: CP

Date/Time 12/12/18 12:45 PM

Received by: CP

Relinquished by: KS