CHEMTECH 284 Sheffield Street, Mountainside New Jersey 07092 NEW JERSEY LAB ID#: 20012: NEW YORK LAB ID#: 11376

METALS CONFORMANCE/NON-CONFORMANCE SUMMARY

MATRIX: TCLP

CHEMTECH PROJECT NUMBER: N1287

METH	HOD: 6010D,7470A,1311			
1.	Calibration Summary met criteria.	NA	NO	YES ✓
2.	ICP Interference Check Sample Results Summary Submitted.			✓
3.	Serial Dilution Summary (if applicable) Submitted.			✓
4.	Laboratory Control Sample Summary (if applicable) Submitted.			✓
5.	Blank Contamination - If yes, list compounds and concentrations in each blank:		✓	
6.	Matrix Spike/Matrix Spike Duplicate Recoveries Met Criteria			\checkmark
	If not met, list those compounds and their recoveries which fall outside the acceptable range.			
7.	Sample Duplicate Analysis Met QC Criteria			\checkmark
	If not met, list those compounds and their recoveries which fall outside the acceptable range.			
8.	Digestion Holding Time Met			\checkmark
	If not met, list number of days exceeded for each sample:			
9.	Analysis Holding Time Met			\checkmark
	If not met, list those compounds and their recoveries which fall outside the acceptable range.			
ADDIT	FIONAL COMMENTS: In analytical sequence LB118538, The % recovery was outside of	acceptan	ce limit 1	for
Barium	of CCV14 But No any sample analyze for this CCVs.			
QA RE	EVIEW Date			